

KNOW YOUR CAR REPORT



Comprehensive Vehicle Analysis & Documentation

VEHICLE DETAILS		SPECIFICATIONS	
REGISTRATION NUMBER	*****	FUEL TYPE	DIESEL
MAKE & MODEL	BMW 320D	TRANSMISSION	AUTOMATIC
MANUFACTURING YEAR	2012	ODOMETER READING	88841 km

SUMMARY / REMARKS

SUMMARY DETAILS

SUMMARY

Valve cover oil leak.
All body repaint.
tyres are 50%.
AC not working.
Turbo leak.
power steering boot leak.
wheel speed sensor error code.
Check EGR.
Odo meter faded.
Needs a general service as it is time to change oil.
door pad handles broken.

DOCUMENTS

COMPONENT	STATUS	REMARKS
Place of Inspection	*****	
RC	ORIGINALAVAILABLE	
Reg No	*****	
Make	BMW	
Model	320D	
Variant	NOT AVAILABLE	
Colour	SILVER	
Fuel Type	DIESEL	No remarks available
Transmission	AUTOMATIC	No remarks available
Manufacturing Year	2012	No remarks available
Date of Registration	1/6/2012	No remarks available
Seating Capacity	5	No remarks available
RTO	MALAPPURAM	No remarks available
ODO READING	88841	No remarks available

COMPONENT	STATUS	REMARKS
Insurance	COPYAVAILABLE	
Insurance Type	THIRDPARTY	
Insurance Expiry Date	4/4/2025	
Number of Ownership	3	
Hyphothecation	YES	
Sale Letter	N/A	
RC OWNER CONTACT	N/A	
NOC	NOTNEEDED	
PARIVAHAN CHECK	DONE	
CHALLAN	AVAILABLE	
BLACKLIST	NOTAVAILABLE	
VEHICLE SERVICE HISTORY	N/A	
PERIODIC SERVICE AS PER VSH	N/A	

COMPONENT	STATUS	REMARKS
ACCIDENTAL REPAIR AS PER VSH	N/A	
MAJOR MECHANICAL REPAIR IN VSH	N/A	
CHASSIS NO	N/A	
ENGINE NUMBER	N/A	

ENGINE

COMPONENT	STATUS	REMARKS
RADIATOR/INTERCOOLER	OK	
LEAKAGE (OIL/FUEL/COOLANT)	YES	
RADIATOR CAP OPEN CHECK	N/A	
AIR FILTER	N/A	
COOLANT	OK	
ENGINE OIL	OK	
COMPRESSION LEAK	N/A	

COMPONENT	STATUS	REMARKS
ABNORMAL VIBRATION	OK	
ABNORMAL ENGINE NOISE	OK	
SMOKE	N/A	
HOSES	OK	
BELTS	OK	

TRANSMISSION

COMPONENT	STATUS	REMARKS
LEAKAGE (GEAR OIL)	NO	
AXLE BOOTS	OK	
PROP SHAFT	N/A	
DIFFERENTIAL (FRONT)	N/A	
DIFFERENTIAL (REAR)	OK	
CLUTCH CONDITION	N/A	

COMPONENT	STATUS	REMARKS
GEAR SHIFTING	SMOOTH	
ABNORMAL NOISE TRANS	NORMAL	

SUSPENSION

COMPONENT	STATUS	REMARKS
FRONT RH SHOCK LEAK	OK	
FRONT LH SHOCK LEAK	OK	
REAR RH SHOCK LEAK	OK	
REAR LH SHOCK LEAK	OK	
ABNORMAL NOISE FRONT	ABNORMAL	
ABNORMAL NOISE REAR	OK	
SUSPENSION COMFORT	OK	

STEERING

COMPONENT	STATUS	REMARKS
POWER STEERING FLUID LEAK	YES	
ALIGNMENT	OK	
POWER STEERING CONDITION	OK	
ABNORMAL STEERING NOISE	OK	

BRAKES

COMPONENT	STATUS	REMARKS
FRONT RH BRAKE	OK	
FRONT LH BRAKE	OK	
REAR RH BRAKE	OK	
REAR LH BRAKE	OK	
BRAKE FLUID CONDITION	OK	
SIDE PULLING ON BRAKING	NO	
HAND BRAKE CONDITION	BAD	

ELECTRICALS

COMPONENT	STATUS	REMARKS
BATTERY SL NUMBER	NOT AVAILABLE	
BATTERY CONDITION	OK	
ALTERNATOR	GOOD	
STARTER	GOOD	
FUSE BOXES	N/A	
AIR CONDITIONING FLOW	OK	
AIR CONDITIONING TEMPERATURE	BAD	
ANTI LOCK BRAKING SYSTEM	N/A	
FUEL PUMP	OK	
ECU SCAN	BAD	
WARNING LAMPS	BAD	
HORN	OK	

COMPONENT	STATUS	REMARKS
HEAD LAMPS	OK	
DIRECTION INDICATORS	OK	
BRAKELAMPS	OK	
WIPER	OK	
FOG LAMPS	N/A	
POWER WINDOW	OK	
SUN ROOF	N/A	
ROOF LAMP	N/A	
VENTILATIONS	OK	
HEATING	BAD	
AUTO FOLDING OF ORVM	N/A	
VENTILATED SEAT	N/A	
INFOTAINMENT SYSTEM	AVAILABLEWORKING	
REVERSE PARKING	N/A	

COMPONENT	STATUS	REMARKS
CRUISE CONTROL/ADAS	N/A	

BODY

COMPONENT	STATUS	REMARKS
HOOD/BONNET	REPAINTED	
ROOF	REPAINTED	
RHS FENDER	REPAINTED	
RHS A PILLAR	OK	
RHS FRONT DOOR	REPAINTED	
RHS B PILLAR	REPAINTED	
RHS REAR DOOR	REPAINTED	
RHS RUNNING BOARD	REPAINTED	
RHS C PILLAR/QUARTER PANEL	REPAINTED	
TAIL GATE/DICKY	REPAINTED	

COMPONENT	STATUS	REMARKS
LHS C PILLAR/QUARTER PANEL	REPAINTED	
LHS RUNNING BOARD	REPAINTED	
LHS REAR DOOR	REPAINTED	
LHS B PILLAR	OK	
LHS FRONT DOOR	REPAINTED	
LHS A PILLAR	OK	
LHS FENDER	REPAINTED	
UNDERBODY	SCRATCH	
RHS APRON	OK	
LHS APRON	N/A	
FRONT CROSS MEMBER	N/A	
FRONT GLASS	OK	
RHS FRONT DOOR GLASS	OK	

COMPONENT	STATUS	REMARKS
RHS REAR DOOR GLASS	OK	
RHS QUARTER GLASS	OK	
TAIL GATE GLASS	OK	
QUARTER GLASS	OK	
LHS REAR GLASS	OK	
LHS FRONT GLASS	OK	
BUMPER FRONT	OK	
REAR BUMPER	OK	
RUBBER BEEDINGS	BAD	
EXTRA FITTINGS/ ALTERATIONS	N/A	
INSIDE REAR VIEW MIRROR	OK	
OUTSIDE REAR VIEW MIRROR RHS	OK	
OUTSIDE REAR VIEW MIRROR LHS	OK	

WHEELS AND TIRE

COMPONENT	STATUS	REMARKS
FRONT RH	6MM+/50%	
REAR RH	6MM+/50%	
STEPNY	N/A	
REAR LH	6MM+/50%	
FRONT LH	6MM+/50%	
ABNORMAL FRONT TIRE WEAR	OK	
OVERALL TIRE CONDITION	OK	
FRONT RH (ALLOY/DISC)	OK	
REAR RH (ALLOY/DISC)	OK	
REAR LH (ALLOY/DISC)	OK	
FRONT LH (ALLOY/DISC)	OK	
STEPNY (ALLOY/DISC)	N/A	

INTERIOR

COMPONENT	STATUS	REMARKS
SEATS	OK	
DASHBOARD	OK	
DOORPADS	OK	
ROOF LINER	BAD	
FLOOR MATS	N/A	

ACCESSORIES

COMPONENT	STATUS	REMARKS
TOOL KIT	NOTAVAILABLE	
JACK	NOTAVAILABLE	

FLOOD SIGNS

COMPONENT	STATUS	REMARKS
Rusted Bolts	NOSIGNS	
Inside Dashboard	NOSIGNS	

COMPONENT	STATUS	REMARKS
Inside Boot/Dicky	NOSIGNS	
Inside AC Vent	NOSIGNS	
Inside Air Filter	NOSIGNS	
Inside Body Panel	NOSIGNS	

CERTIFICATION STATUS

CERTIFICATION DETAILS

STATUS	APPROVED
INSPECTED BY	Rakesh MR
INSPECTION DATE	05 Jun 2025, 10:52 PM
APPROVED BY	Technical Head
APPROVAL DATE	05 Jun 2025, 11:33 PM

DISCLAIMER

This report (report means product or/and services provided to the customer) is based on the condition of the vehicle on the date of inspection and provides an approximate estimate of the condition on that date. CERTIFIDE has relied on the odometer reading for KMs driven as seen at the time of inspection and is not responsible for verifying its genuineness. Except where indicated the parts were in working condition - this report does not take into account the condition of the parts which are not visible or not inspected. The report is in no way a commitment to the condition of the vehicle. All reports are subjective and CERTIFIDE and its associates cannot

be held liable in any way due to the use of this report in any way. At no time CERTIFIDE and its associates have any obligations or liabilities in respect of transactions originated on the basis of this report. The price and other terms of any sale of the vehicle shall remain subject to direct negotiation between buyer and seller.

Report generated by Certifide Vehicle Inspection System

Page

© 2026 Certifide. All rights reserved.

